

## RELEASE NOTES:

20241010 - Cherry Utility Software\_x32 v3.6.1

### CHANGES IN V3.6.1 FROM 2024/10/10:

- Support for MX 3.0S TKL RGB - JIS Version
- Support for MX 1.0 TKL RGB - ANSI
- M50 Wireless - new FW v0127
- M50 Wireless (Dongle): Integrated native FW-Update
- Introduced support for Japanese and Ukrainian languages in the application interface
- Enhanced tooltip visuals
- Bug fixes:
  - App name and icon inconsistency – Resolved the issue of inconsistent display in Windows “Apps and Features.”
  - Modifier keys issue on MX 2.1 / LP 6.1 – Fixed the inability to map keys to modifier functions
  - German translation fixes – Adjusted button borders in the macro table to fit text correctly
  - M50 Wireless: Default Sleep time had an incorrect value
  - Various smaller fixes and improvements

### FEATURES MISSING FOR NOW:

- User notification about future software updates
- Automatic software update, when new software version is available
- “Text” Action not yet supported for M50 wired
- Native implementation of Firmware update for M50 wired (currently, external .exe is called)

### SUPPORTED DEVICES:

- G80-3000n FS RGB - ANSI & ISO
- G80-3000n TKL RGB - ANSI & ISO
- G80-3000S TKL RGB - ANSI
- G80-3000S TKL NBL - ANSI
- G80-3000S FS RGB - ANSI & KR Version
- MC 2.1
- MC 3.1 v1 (new Sensor - 3333)
- MC 3.1 v2 (old Sensor - 3310)
- M50 Wireless RGB (RF Dongle & Cable)

- M50 Wired (non-RGB)
- MV 3.0 FS RGB - ANSI
- MX 1.0 TKL NBL - ANSI
- MX 1.0 TKL RGB - ANSI
- MX 1.1 TKL RGB - ANSI
- MX 1.1 TKL NBL - ANSI
- MX 10.0 RGB - ANSI
- MX 10.0n RGB - ANSI & ISO
- MX 2.0S FS RGB - ANSI & ISO
- MX 2.0s FS NBL - ANSI
- MX 2.0s FS Wireless NBL - ANSI
- MX 3.0S FS RGB - ANSI & ISO + KR Version
- MX 3.0S FS NBL - ANSI & ISO
- MX 3.0S TKL RGB - ANSI & KR & JIS Version
- MX 3.0S TKL NBL - ANSI
- MX 3.0S FS Wireless RGB - ANSI & ISO
- MX 3.1 FS RGB - ANSI & ISO
- MX 8.2 TKL Wireless RGB - ANSI & ISO
- MX 8.2 XAGA Wireless TKL RGB - ANSI
- MX-LP 2.1 Wireless RGB - ANSI & ISO
- MX-LP 6.1 Wireless RGB - ANSI